



WASHING INSTRUCTIONS MOP AND CLOTH

**WASH SEPARATELY.
DO NOT USE FABRIC SOFTENER!**

	MAXIMUM WASHING TEMPERATURE	MAXIMUM DRYER TEMPERATURE	BLEACHING
MOP QUALITY GRADES			
TRONIC, TRONIC LIGHT, GREEN TRONIC			
WHITE MAGIC, GREEN MAGIC			
CERAN			
BRUSH, BRUSH PROGRESSIVE, GREEN BRUSH PROGRESSIVE			
CLASSIC, BASIC, BASIC LIGHT, GREEN BASIC			
ANTIBAK			
BLUE, RED			
PROGRESSIVE			
UNIVERSAL ONE			
CLOTH QUALITY GRADES			
TEXTRONIC, SOFTTRONIC, SOFTY, PROGRESSIVE			
MULTI-PURPOSE-FLEECE CLOTH			

LEGEND Do not tumble dry Max 60°C Max 95°C Oxygen bleaching